

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard Hamilton Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River Hamilton Bend	Right	3.39	09/06/2018 09/06/2018	Sterling York

LM Start		Rating **	A	Issue No.	7
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Operations & Maintenance Manuals			°	°
DWR ID	DWR_ST0005_01_s_2013_7				
Comment Code					
Inspector Comment					
O&M manual is located at the Sutter Maintenance Yard.					

No Photos

LM Start		Rating **	A	Issue No.	8
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Emergency Supplies & Equipment			°	°
DWR ID	DWR_ST0005_01_s_2013_8				
Comment Code					
Inspector Comment					
Emergency supplies and equipment are stored at the Sutter Maintenance Yard.					

No Photos

LM Start		Rating **	A	Issue No.	9
LM End		Issue Type +	Ma	Location *	
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Flood Preparedness & Training			°	°
DWR ID	DWR_ST0005_01_s_2013_9				
Comment Code					
Inspector Comment					
Sutter Maintenance Yard employees attend the annual Flood Fight class put on by DWR inspector Bob Duffy.					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable	N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	--	---	---

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard Hamilton Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River Hamilton Bend	Right	3.39	09/06/2018 09/06/2018	Sterling York

LM Start	0.02	Rating **	A	Issue No.	3
LM End	1.21	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.439960 °	39.456723 °
				-121.641439 °	-121.639323 °
DWR ID	DWR_ST0005_01_f_2018_3				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Maintained annual vegetation, this section is sprayed but not mowed due to the cobbles, Fall 2018.					

Photo 1 of 1 : FA_2018_ST0005_289_3_20181003_00015.jpg



View looking upstream landside of the maintained annual vegetation, this section is sprayed but not mowed due to the cobbles, Fall 2018.

LM Start	0.02	Rating **	A	Issue No.	5
LM End	1.21	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.439960 °	39.456723 °
				-121.641439 °	-121.639323 °
DWR ID	DWR_ST0005_01_f_2018_5				
Comment Code					
V1 : Control annual grass and weeds on the levee slopes and easements.					
Inspector Comment					
Maintained annual vegetation, this section is sprayed but not mowed due to the cobbles, Fall 2018.					

Photo 1 of 1 : FA_2018_ST0005_289_5_20181003_00016.jpg



View looking upstream waterside of the maintained annual vegetation, this section is sprayed but not mowed due to the cobbles, Fall 2018.

LM Start	0.19	Rating **	M	Issue No.	15
LM End	0.19	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Vegetation			39.442435°	39.442435°
				-121.641760°	-121.641760°
DWR ID	DWR_ST0005_01_s_2015_15				
Comment Code					
V4 : Elderberries are blocking visibility and flood fight capability.					
Inspector Comment					

No Photos

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown		** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable		+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement	
		N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain			

Sutter Maintenance Yard Hamilton Bend

No Photos

View looking upstream waterside of trees. Small trees 4" in diameter at chest height have been sprayed and should be removed, Spring 2018.

Page 3 of 6

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard Hamilton Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River Hamilton Bend	Right	3.39	09/06/2018 09/06/2018	Sterling York

LM Start	1.48	Rating **	U	Issue No.	18
LM End	1.99	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.458053 °	39.461949 °
				-121.636300 °	-121.629563 °
DWR ID	DWR_ST0005_01_s_2017_18				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
From Levee Mile 1.38 to 3.39 has never been maintained by the LMA.					

Photo 1 of 1 : FA_2018_ST0005_289_18_20180918_00007.jpg



View looking upstream of thick trees and vegetation blocking visibility on waterside, looking downstream. Spring 2018.

LM Start	1.48	Rating **	U	Issue No.	11
LM End	3.25	Issue Type +	Ma	Location *	LS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.458055 °	39.470312 °
				-121.636300 °	-121.609242 °
DWR ID	DWR_ST0005_01_s_2017_11				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
From Levee Mile 1.38 to 3.39 has never been maintained by the LMA.					

Photo 1 of 1 : FA_2018_ST0005_289_11_20181003_00014.jpg



View looking upstream landside and waterside of thick trees blocking visibility on landside, Fall 2018.

*** Location**

LS : Land Side N/A : Not Applicable
WS : Water Side
CR : Crown

**** Rating**

A : Acceptable N : Not Inspected/Rated
M : Minimally Acceptable C : Corrected
U : Unacceptable A/W : Acceptable but Monitor & Maintain

+ Issue Type

Ma : Maintenance Deficiency
Ob : Design & System Obsolescence
En : Enforcement

Sutter Maintenance Yard Hamilton Bend

* Location	** Rating	+ Issue Type
LS : Land Side N/A : Not Applicable	A : Acceptable N : Not Inspected/Rated	Ma : Maintenance Deficiency
WS : Water Side	M : Minimally Acceptable C : Corrected	Ob : Design & System Obsolescence
CR : Crown	U : Unacceptable A/W : Acceptable but Monitor & Maintain	En : Enforcement

**Flood Control Project Maintenance
Levee Inspections**

Maintenance Issue Types Only, Levee Inspection Report By Mile - Fall 2018

Sutter Maintenance Yard Hamilton Bend

Waterway	Bank	Unit Miles	Inspection Start/End	Inspector
Unit No. 01 Feather River Hamilton Bend	Right	3.39	09/06/2018 09/06/2018	Sterling York

LM Start	3.23	Rating **	M	Issue No.	4
LM End	3.27	Issue Type +	Ma	Location *	WS
Category	Earthen Levee			GPS Latitude/Longitude	
				Start	End
Item	Trim / Thin Trees			39.470063 °	39.470558 °
				-121.609264 °	-121.609215 °
DWR ID	DWR_ST0005_01_s_2013_4				
Comment Code					
T3 : Trim and thin trees to allow visibility of the ground and room to flood fight.					
Inspector Comment					
Small trees 4" in diameter at chest height should be removed before they get too big. From Levee Mile 1.38 to 3.39 has never been maintained by the LMA.					

Photo 1 of 1 : FA_2018_ST0005_289_4_20180918_00001.jpg



View looking upstream waterside of small trees 4" in diameter at chest height should be removed before they get to big, Spring 2018.

* Location LS : Land Side N/A : Not Applicable WS : Water Side CR : Crown	** Rating A : Acceptable M : Minimally Acceptable U : Unacceptable N : Not Inspected/Rated C : Corrected A/W : Acceptable but Monitor & Maintain	+ Issue Type Ma : Maintenance Deficiency Ob : Design & System Obsolescence En : Enforcement
--	---	---